
Document ID: EDF-ER-276

Revision ID: 1

Effective Date: 05/14/02

Engineering Design File

Evaluation of Geotechnical Investigations Required to Complete Design and Construction



431.02 06/20/2001 Rev. 09

ENGINEERING DESIGN FILE

EDF-	ER-276
Rev. No.	1
	Page 1 of 2

1.	Title: Evaluat	ion of C	Geotechnical Investiga	itions Req	uired to Comp	olete Design and	Construction	
2.	Project File No	.: NA						
3.	Site Area and	Building	No.: NA	4. SSC	Identification/I	Equipment Tag N	lo.: NA	
5.	As part of the work to prepare the drawings, specifications, and calculations/studies for the INEEL CERCLA Disposal Facility (ICDF), an evaluation of the existing geotechnical information was performed. In general, the existing geotechnical information is thorough and complete. The existing information provides a strong base for the preparation of the Title I Design and completion of the remedial design/construction work plan (RD/CWP). However, in development of the design studies and calculations for slope stability assessment, fate and transport modeling, and final cover hydraulic modeling and life cycle evaluation, specific data gaps requiring additional geotechnical testing, investigation, or survey were identified.							
	calculations (in provides the e	ncluding ngineer	able provides a summ I laboratory testing) re ing design file (EDF) type and quantity of	equired to number ar	complete the nd justification	RD/CWP. The s for the additiona	ummary table	
	Some of the additional testing has been performed in subsequent design phases for the ICDF. Additional interface shear tests were performed as recommended. Results of this additional testing are provided in "Slope Stability Assessments" (EDF-ER-268).							
	Geological observations during the Phase I excavation of the ICDF in Summer 2001 and additional borings were performed by BBWI in the landfill footprint to further define bedrock elevations and sediment thickness.							
6.			oval (A) and Acceptar lefinitions of terms an			ıres.)		
	,	R/A	Typed Name/Orga			Signature , /	Date	
Per	former		Mike Reimbo CH2M HILL		MM	Redul	05/14/02	
Che	ecker	R	(Same as Independ Reviewer)	ent Peer		7	05/14/02	
	ependent Peer viewer	A	Marty Doornb BBWI	os/	Monto	founds	05/14/02	
Apı	orover	Α	Thomas Borso BBWI	hel/	Mun	1 Bul	05/14/02	
Re	Requestor Ac Don Vernon/ BBWI D. Vern 05/14/02							
7.								
8.	B. Records Management Uniform File Code (UFC):							
	Disposition Authority: Retention Period:							
	EDF pertains to NRC licensed facility or INEEL SNF program?: Yes No							

431.0	02
06/2	0/2001
Roy	nα

ENGINEERING DESIGN FILE

EDF- ER-276 Rev. No. 1 Page 2 of 2

9.	Registered Professional Engineer's Stamp (if required)

ACRONYMS

ASTM American Society for Testing Materials

BBWI Bechtel BWXT Idaho, LLC

CERCLA Comprehensive Environmental Response, Compensation, and Liability Act

EDF engineering design file

GCL geosynthetic clay liner

HDPE high-density polyethylene

ICDF INEEL CERCLA Disposal Facility

INEEL Idaho National Engineering and Environmental Laboratory

RD/CWP remedial design/construction work plan

TBD to be determined

iv

Table 1. Draft evaluation of geotechnical investigations and calculations required to complete design and construction.

s	Results of site-specific interface direct shear testing will be used to verify that material strengths used in slope stability assessments and seismic evaluation are appropriate. Values used in current analysis are based on conservative assessment of available data from similar projects, technical literature, and manufacturers, thus the likelihood of lower sitespecific test results impacting the conclusions of the slope stability assessments is considered low.	Construction Interface Documents for this additional testing (items 1a through 1f) were prepared and recommended testing was completed in subsequent design phases. Results of additional site-specific interface shear testing (items 1a through 1f) are reported in "Slope Stability Assessments" (EDF- 268).	One test each required at low (less than 600 psf) and high normal confining stress (2,000 to 10,000 psf).
No. Tests			6
Test Standard			ASTM D5321ª
Justification for Additional Investigation, Testing or Calculation	Slope Stability Assessment and Seismic Evaluation of Lining System have been performed using interface strength characterization data for the geosynthetics from previous projects, the technical literature, and manufacturers. Variability in test setup and products used in this data require that site-specific testing on lining system products be performed to verify the strength parameters used for lining system interfaces. Test requirements are based on the double composite lining system with a geosynthetic clay liner (GCL).		See 1. Above
Related EDF No.	Engineering design file (EDF)-ER-268 and EDF-ER-282		EDF-ER-268 and EDF-ER-282
Additional Investigation, Testing or Calculation No.	1 Site-Specific Interface Engineering Direct Shear Testing on design file Lining System (EDF)-ER- Geosynthetics (individual 268 and interface tests required listed EDF-ER-282 below)		la Operating Layer Soil/Geocomposite

4	
4	9
- 5	2
bouring	Ξ
Ş	Ξ
΄,	5
`	_
	•
,	υ
3	ט
ŕ	V

	Comments	One test each required at low (less than 600 psf) and high normal confining stress (2,000 to 10,000 psf).	One test each required at low (less than 600 psf) and high normal confining stress (2,000 to 10,000 psf).	One test each required at low (less than 600 psf) and high normal confining stress (2,000 to 10,000 psf).	Required at high normal (2,000 to 10,000 psf) confining stress only.	One test each required at low (less than 600 psf) and high normal confining stress (2,000 to 10,000 psf).	Approximated quantities of material needed for Items 2a and 2b will be provided to Bechtel BWXT Idaho, LLC (BBWI) in to assist in borrow area determination. Revised quantities of materials based on the 90% RD/CWP design submittal will be provided to BBWI under separate cover.
	No. Tests	6	6	2	-	7	
	Test Standard	ASTM D5321 ^a	ASTM D5321 ^a ASTM D6243 ^b	ASTM D5321 ^a ASTM D6243 ^b	ASTM D5321 ^a ASTM D6243 ^b	ASTM D5321ª	
	Instification for Additional Related Investigation, Testing or EDF No. Calculation	EDF-ER-268 See 1. Above and EDF-ER-282	EDF-ER-268 See 1. Above and EDF-ER-282	EDF-ER-268 See 1. Above and EDF-ER-282	EDF-ER-268 See 1. Above and EDF-ER-282	EDF-ER-268 See 1. Above and EDF-ER-282	EDF-ER-279 and EDF-ER-281
Table 1. (continued)	Additional Investigation, Testing or Calculation	Geocomposite/Text highdensity polyethylene (HDPE) Geomembrane	1c Text HDPE Geomembrane/Nonwoven GCL	1d Nonwoven GCL/Geocomposite	1e GCL Internal Shear	1f Text HDPE Geomembrane/Soil bentonite liner	2 Site-specific data for final cover soil/rock needed for Final Cover Life Cycle and Hydrologic Modeling studies

Tab	Table 1. (continued)					
Š	Additional Investigation, Testing or Calculation Required	Related EDF No.	Justification for Additional Investigation, Testing or Calculation	Test Standard	No. Tests	Comments
] ≱ ≨	EDF-ER-279 and EDF-ER-281	The INEEL CERCLA Disposal Facility (ICDF) landfill final cover may include a soil layer to provide water storage. Soil consisting of a silty loam provides good water storage. Potential borrow sources need to be identified and characterized to determine applicability for a water storage soil source for the final cover.	Specific test requirements.	To be Site-spec determined required. (TBD)	Site-specific investigations are required.
26	2b Riprap armor source	EDF-ER-281	The ICDF landfill final cover may include rock armoring for the sideslopes and biointrusion layers. A rock borrow source needs to be identified and characterized. Durability testing should be performed on rock that will be exposed on the landfill cover.	Specific test requirements (TBD)	TBD	A review of existing information including nearby pits should be evaluated prior to performing intrusive activities.
æ	Additional geotechnical quality control test results for the test pad	Not Applicable	During Phase 1 construction, CH2M HILL performed many quality control tests on the completed test pad and test pad soils. This additional data is intended to supplement data presented in EDF-2899.	ASTM standards were used for all geotechnical testing.	Not Applicable	Not Geotechnical test results from Applicable Phase I construction performed by CH2M HILL are included in Appendix A.

-	_
•	(Continued)
	ã
	~
	-
	Ω
•	-
	÷
	5
	•
	ř
	٠,
	_
•	
	Λ
	4
	•
•	2
	c
	_

Comments	Geotech data obtained during excavation activities are presented in Appendix B.	
No. Tests	Õ Š Ä	
Test Standard No. Tests	Not Applicable	
Justification for Additional Investigation, Testing or Calculation	During excavation of ICDF Cell 1 in Summer 2001, geologic observations were recorded by BBWI geologist. In addition, at completion of Phase I excavation, BBWI performed additional borings within the ICDF Cell 1 footprint to further define bedrock elevation and sediment thickness.	This additional data is intended to supplement data presented in the ICDE George-huisal Report
Related EDF No.	Not Applicable	
Additional Investigation, Testing or Calculation No. Required	4 Additional geologic/geotechnical data for ICDF	

ASTM D5321 - Standard Test Method for Determining the Coefficient of Soil and Geosynthetic or Geosynthetic and Geosynthetic Friction by the Direct Shear Method

ASTM D6243 - Standard Test Method for Determining the Internal and Interface Shear Resistance of Geosynthetic Clay Liner by the Direct Shear Method

ICDF Geotechnical Report.

REFERENCES

ASTM D5321-92, 1992 (1997), "Standard Test Method for Determining the Coefficient of Soil and Geosynthetic or Geosynthetic and Geosynthetic Friction by the Direct Shear Method," American Society for Testing and Materials, (reapproved 1997).

ASTM D6243-98, 1998, "Standard Test Method for Determining the Internal and Interface Shear Resistance of Geosynthetic Clay Liner by the Direct Shear Method," American Society for Testing and Materials, 1998.

EDF-ER-268, 2002, "Slope Stability Assessments," Rev. 1, Environmental Restoration Program, Idaho National Engineering and Environmental Laboratory, May 2002.

EDF-ER-279, 2002, "Hydrologic Modeling of Final Cover," Rev. 2, Environmental Restoration Program, Idaho National Engineering and Environmental Laboratory, May

EDF-ER-281, 2002, "Liner and Final Cover Long-Term Performance Evaluation and Final Cover Life Cycle Expectation," Rev. 1, Environmental Restoration Program, Idaho National Engineering and Environmental Laboratory, May 2002.

EDF-ER-282, 2002, "Seismic Evaluation of Landfill and Evaporation Pond," Rev. 1, Environmental Restoration Program, Idaho National Engineering and Environmental Laboratory, May 2002.

EDF-2899, 2002, "Test Pad Post-Construction Report," Rev. 0, Environmental Restoration Program, Idaho National Engineering and Environmental Laboratory, May 2002.

ä